

Scanner Funktionstest nach Programmierung



Nach Programmieren des Scanners sollte folgendes an den Strichcode angefügt werden.

Pos.	Barcode	Erwartete Ausgabe im Editor/Notepad
1	 2 900020 070008	4B2900020070008
2	 7300000015600000165000000150	4T7300000015600000165000000150
3	 0 75380 05606 0	4C075380056060
4	 4008 4329	4A40084329

Pos.	Barcode	Erwartete Ausgabe im Editor/Notepad
5	 1234567890	4N1234567890

Revision #1

Created 21 February 2024 09:02:38

Updated 2 April 2024 10:55:16